

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 1 710 East 3rd Avenue (Residence).

Direction: Northwest

Date: 2/24/14

Time: 12:51

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 2 Water heater in utility room. Note derelict wiring to right.

Direction: West

Date: 2/22/14

Time: 11:19

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 3 Chimney in utility room.

Direction: Northwest

Date: 2/22/14

Time: 11:20

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 4 Furnace in utility room. Note steel pipe-to-plastic gas line, and wiring to left.

Direction: West/Down

Date: 2/22/14

Time: 11:20




Photo 5 Plugged sump on utility room floor.

Direction: Down

Date: 2/22/14

Time: 11:20

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 6 Sewer pipes to utility room floor.

Direction: South/Down

Date: 2/22/14

Time: 11:20

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 7 Forced air heating duct into crawl space.

Direction: Northeast

Date: 2/22/14

Time: 11:20



Photo 8 Forced air heating duct into crawl space.

Direction: North

Date: 2/22/14

Time: 11:21

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 9 Storage in crawl space, furnace & heating ducts.

Direction: North

Date: 2/22/14

Time: 11:26



Photo 10 Washer and dryer in utility room.

Direction: Southeast/Down

Date: 2/22/14

Time: 11:26

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck



Photo 11 Sewer pipe, washer and sink in utility room.

Direction: South

Date: 2/22/14

Time: 11:26




Photo 12 Sewer pipe beneath sink to utility room floor.

Direction: Southeast/Down

Date: 2/22/14

Time: 11:26

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck

(b) (6)



Direction: South

Date: 2/22/14

Time: 11:26

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck




Photo 14 Stairwell and door to utility room.

Direction: South

Date: 2/22/14

Time: 11:27

SUBAREA II FOURTH AVENUE AND GAMBELL STREET REMOVAL ACTION

710 East 3rd Street
Anchorage, Alaska

TDD Number: 13-08-0020
Photographed by: Carl Overpeck

(b) (6)



Photo 15 North Bedroom.

Direction: North

Date: 2/25/14

Time: 16:10
